Material Safety Data Sheet
May be used to comply with
Administration
OSHA's Hazard Communication Standard,
29 CFR 1910.1200. Standard must be
consulted for specific requirements.

U.S. Department of Labor
Occupational Safety and Health

(Non-Mandatory Form)
Form Approved
OMB No. 1218-0072

IDENTITY *(As Used on Label and List)*	NOTE: Blank spaces are not permitted. If any item is not applicable, or no information is available, the space must be marked to indicate that.
Interface Light Cured Cavity Liner	

Section I

Manufacturer's Name Temrex Corporation	**Emergency Telephone Number** (800) 645-1226
Address *(Number, Street, City, State, and ZIP Code)* 112 Albany Avenue	**Telephone Number for Information** (516) 868-6221
P.O. Box 182	**Date Prepared** January 24, 2011
Freeport, NY 11520	**Signature of Preparer** *(optional)*

Section II – Hazardous Ingredients/Identity Information

Hazardous Components (Specific Chemical Identity: Common Name(s))	OSHA PEL	Other Limits ACGIH TLV	Recommended	%(optional)
None listed.				

Section III – Physical/Chemical Characteristics

Boiling Point Above 200°C.		**Specific Gravity** *(H2O = 1)* N/A
Vapor Pressure *(mm Hg.)* 30mm Hg at 20°C.		**Melting Point** N/A
Vapor Density *(AIR = 1)* 1		**Evaporation Rate** *(Butyl Acetate = 1)* N/A
Solubility in Water Virtually insoluble.		
Appearance and Odor Light paste; slight, specific odor.		

Section IV – Fire and Explosion Hazard Data

Flash Point *(Method Used)* Above 150°C closed cup.	**Flammable Limits** N/A	**LEL** N/A	**UEL** N/A
Extinguishing Media Water spray, CO2, Foam are all acceptable.			
Special Fire Fighting Procedures No particular procedure.			
Unusual Fire and Explosion Hazards None			

(Reproduce Locally)
1985

OSHA 174, Sept.

Section V – Reactivity Data

Stability	Unstable		Conditions to Avoid
	Stable	X	Avoid exposure to elevated temperatures and high intensity light.
Incompatibility *(Materials to Avoid)* Free radical initiator, when stored in bulk.			
Hazardous Decomposition or Byproducts None			
Hazardous Polymerization	May Occur		Conditions to Avoid
	Will Not Occur	X	Avoid extreme temperature or light when stored in bulk.

Section VI – Health Hazard Data

Route(s) of Entry:	Inhalation?	Skin?	Ingestion?
	N/A	Yes	Yes

Skin: Wash with copious amounts of water. Eyes: Flush with copious amounts of water.

Ingestion: Acute toxic effects are unlikely.

Health Hazards *(Acute and Chronic)*

None known.

Carcinogenicity:	NTP?	IARC Monographs?	OSHA Regulated?
	N/A	N/A	N/A

Signs and Symptoms of Exposure

None known.

Medical Conditions Generally Aggravated by Exposure

None known.

Emergency and First Aid Procedures

None

Section VII – Precautions for Safe Handling and Use

Steps to Be Taken in Case Material is Released or Spilled

Wipe up; incinerate large quantities.

Waste Disposal Method

Incinerate if large quantities are involved.

Precautions to Be Taken in Handling and Storing

Avoid prolonged exposure to temperatures above 30°C and light.

Other Precautions

None

Section VIII – Control Measures

Respiratory Protection *(Specify Type)* Not required.		
Venthilation	Local Exhaust N/A	Special N/A
	Mechanical *(General)* N/A	Other N/A
Protective Gloves Required only when working with bulk quantities.		Eye Protection Only with bulk quantities.
Other Protective Clothing or Equipment Not required under normal handling.		
Work/Hygienic Practices Avoid contact with skin; if it occurs, wash immediately with soap and water.		

* U.S.G.P.O.: 1966 – 491 –

529/45775